



OLENE S. WALKER  
Governor  
GAYLE F. McKEACHNIE  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

ROBERT L. MORGAN  
Executive Director

LOWELL P. BRAXTON  
Division Director

Supervisor DOZ

### Inspection Report

#### Minerals Regulatory Program

Report Date: September 10, 2004

**Mine Name:** ECDC Clay Mine

**Operator or Permittee Name:**

ECDC Environmental

**Permittee Mailing Address:**

1111 West Hwy. 123, P. O. Box 69, East Carbon,  
Utah 84520

**Inspector(s):** Paul Baker

**Other Participants:** None

**Permit Status:** Inactive

**Current Acreages:**

**Total Permitted (Bonded):** 25

**Total Disturbed:** Not measured

**Permit number:** M/015/062

**Inspection Date:** June 30, 2004

**Weather:** Mostly clear, 80's

**Inspection Start Time:** Abt. 12:15 PM

**Inspection End Time:** Abt. 1:45 PM

**Site location/Area Inspected (i.e. Pit #):**

Entire site

**Surface Ownership:** Fee

**Mineral Ownership:** Fee

**Mineral Mined:** Clay

**Type of Mine:** Surface

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: June 30, 2004; Report Date: September 10, 2004  
Page 2 of 2  
M/015/062

**Purpose of Inspection:**

This was a routine inspection with no specific purpose other than to check the site.

**Inspection Summary:**

**3. Protection of Drainages**

This site is immediately adjacent to the Price River, and there is a drainage that receives runoff from a fairly large upstream area. There is a culvert where this drainage crosses the entrance road, and the culvert inlet needs to be cleaned out.

In 2001, I asked the operator to install sediment control along a section of an overburden pile, and a row of straw bales was placed along the base of this pile. These bales have deteriorated and probably control little sediment (Photo 3). Although I considered asking the operator to maintain these straw bales, the overburden pile and adjacent riparian area look almost identical to a nearby undisturbed area (Photo 4). Therefore, I do not feel there is a need to maintain the straw bales, but the Division and the operator should monitor this area for accelerated erosion and sediment additions to the river.

There is a berm separating much of the site from the Price River, but at the bottom of the hill from the entrance gate, there is an area where the berm has been breached (Photos 1 and 2). This needs to be repaired, and the operator may want to consider an alternative other than just building up the berm. It might be good to install a notched, wire-reinforced silt fence to allow some discharge while still controlling sediment.


**12. Soils**

The soil pile is shown in Photo 5. The operator needs to ensure that this material is not used for anything other than reclamation, and I suggest putting a sign on the pile advising people that it is topsoil. I also suggest that the operator try to establish vegetation on this pile. The next time equipment is brought to the mine, the pile could be worked so it is very rough without the near-vertical slopes. It could then be seeded.

**GPS data:**

I did not take GPS data.

**Inspector's Signature**



**Date:** Sept. 10, 2004

**PBB:jb**

**cc:** Darin Olson, ECDC  
O:\M015-Emery\M0150062-ECDC\inspection\ins-06302004.doc



**ATTACHMENT  
Photographs**

**M/015/062, ECDC Clay Mine, ECDC Environmental**

**Inspection Dated: June 30, 2004; Report Dated: September 10, 2004**



**Photo 1. A breach in the berm near the bottom of the hill by the entrance gate.**



**Photo 2. This is where water flows into the Price River after going through the breach shown in Photo 1.**



**Photo 3. The remains of straw bales along the overburden/spoil pile.**



**Photo 4. A nearby undisturbed area with a nearly-barren slope ending at the riparian area next to the river.**





**Photo 5. The topsoil stockpile.**



**Photo 6. A panorama taken from the southeast part of the site. The straw bales in Photo 3 are in the left center of this photo.**